

## Notice of Termination of Repair Service

Dear Valued Customers:

We regret to inform you that we will no longer provide our repair service for the following product, which was discontinued in 2019.

We sincerely appreciate your longstanding support in promoting our products as well as your continued patronage. We remain committed to enhancing our services to meet your expectations and look forward to your continued business.

• **Date of Termination of Repair Service**

December 24, 2026 (Product to be received by this date)

• **Applicable Product**

Electric Micro Grinder: LUSTER for ELECTER E-max **NLS-100**

• **Successor Models**

Emax EVOlution Series

<p><b>LUSTER: NLS-110</b> Code No. 1483</p>  <a href="https://en.nakanishi-spindle.com/product/nls-110/">https://en.nakanishi-spindle.com/product/nls-110/</a>	<p><b>Emax EVOlution Controller: NE249</b> 230V: Code No. 8227 120V: Code No. 8224</p>  <a href="https://en.nakanishi-spindle.com/product/ne249/">https://en.nakanishi-spindle.com/product/ne249/</a>
--	--

**Note:** The NLS-110 is not compatible with the ELECTER E-max Controller (NE129).

It must be used with the Emax EVOlution Controller (NE249).

For inquiries regarding the termination of repair service or recommended replacements for this product, please do not hesitate to contact us or your local distributor.

Sincerely,



Akio Matsugi

General Manager  
Industrial Sales Department  
NAKANISHI INC.